

U.S. Department of Transportation

1200 New Jersey Avenue SE Washington, DC 20590

# National Highway Traffic Safety Administration

May 1, 2018

Mr. Matt Feinstein Regulatory Compliance Manager Ducati North America 448 E. Middlefield Road Mountain View, CA 94043 NEF-150JK 18V-239

Subject: Fuel Leak from Tank Breathing System Valve Plug

Dear Mr. Feinstein:

This letter serves to acknowledge Ducati North America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

#### Makes/Models/Model Years:

**DUCATI/PANIGALE V4/2018** 

Mfr's Report Date: April 16, 2018

NHTSA Campaign Number: 18V-239

## **Components:**

FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY

**Potential Number of Units Affected:** 692

#### **Problem Description:**

Ducati North America (Ducati) is recalling certain 2018 Ducati Panigale V4, Panigale V4 S, and Panigale V4 Speciale motorcycles. Fuel may leak from the gas tank's internal breathing system valve plug.

### **Consequence:**

A fuel leak in the presence of an ignition source can increase the risk of a fire.

## Remedy:

Ducati will notify owners, and dealers will replace the plug and the O-ring, free of charge. The recall is expected to begin May 17, 2018. Owners may contact Ducati customer service at 1-888-391-5446.

#### **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

