

**April 27, 2018**

Version 1

## Safety Recall: Incorrect Installation of the Takata Front Passenger's Airbag Inflator

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2003-07	Accord	ALL	Check the iN VIN status for eligibility.
2001-05	Civic	ALL	Check the iN VIN status for eligibility.
2002-06	CR-V	ALL	Check the iN VIN status for eligibility.
2003-11	Element	ALL	Check the iN VIN status for eligibility.
2007	Fit	ALL	Check the iN VIN status for eligibility.
2002-04	Odyssey	ALL	Check the iN VIN status for eligibility.
2003-08	Pilot	ALL	Check the iN VIN status for eligibility.
2012	Ridgeline	ALL	Check the iN VIN status for eligibility.

### BACKGROUND

Some dealers incorrectly installed inflators under Service Bulletins 16-047, Safety Recall: Takata Front Passenger's Airbag Inflator (Phase 1) and 17-001, Safety Recall: Takata Front Passenger's Airbag Inflator (Phase 2). If an airbag is incorrectly installed, and the vehicle is involved in a crash, the airbag will not operate as designed to protect the occupant, leading to increased potential for injury or death. Affected vehicles are on **STOP SALE** until further notice.

Do not call Tech Line for updates.

**This bulletin will be revised in the future once the repair procedure, parts information, and warranty claim information are available.**

END

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.