



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 5, 2018

Mr. Fred Imundo
Compliance Coordinator
Navistar, Inc.
2701 Navistar Dr.
Lisle, IL 60532

NEF-150MR
18V-306

Subject: Brake Drum Overheating and Cracking

Dear Mr. Imundo:

This letter serves to acknowledge Navistar, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

INTERNATIONAL/LT/2019

Mfr's Report Date: May 11, 2018

NHTSA Campaign Number: 18V-306

Components:

SERVICE BRAKES, AIR
SERVICE BRAKES, AIR:DRUM:SHOES/LININGS

Potential Number of Units Affected: 149

Problem Description:

Navistar, Inc. (Navistar) is recalling certain 2019 International LT heavy diesel trucks equipped with feature codes 29WAY, 504312, and 504455. The lightweight brake drums with slack adjusters may drag against the brakes causing the drums to overheat which can result in the brake drum cracking, separating from the vehicle or the brakes becoming inoperative.

Consequence:

If the brake drum separates or if the brakes become inoperative, it can increase the risk of a crash.

Remedy:

Navistar has notified owners, and dealers will replace the brake drums and slack adjusters and replace the brake linings, free of charge. The recall began on May 23, 2018. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 18507.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with a long horizontal stroke at the end.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement