

U.S. Department of Transportation

National Highway Traffic Safety Administration

June 13, 2018

Mr. James Triana Warranty Director Foretravel, Inc. 1221 N.W. Stallings Drive Nacogdoches, TX 75964

llings Drive

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150MR

18V-349

Subject: Missing Passenger Seat Base Securing Bolts

Dear Mr. Triana:

This letter serves to acknowledge Foretravel, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FORETRAVEL/IH45/2017-2018 FORETRAVEL/REALM/2017-2018

Mfr's Report Date: May 29, 2018

NHTSA Campaign Number: 18V-349

Components:

SEATS

Potential Number of Units Affected: 19

Problem Description:

Foretravel, Inc. (Foretravel) is recalling certain 2017-2018 Foretravel iH45 and Realm motorcoaches. The passenger seat base assembly may not be adequately secured.

Consequence:

In the event of a crash, the passenger seat base may move, increasing the risk of occupant injury.

Remedy:

Foretravel will notify owners, and dealers will install any missing bolts, free of charge. The recall is expected to begin June 15, 2018. Owners may contact Foretravel customer service at 1-800-955-6226.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received Foretravel's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As required in Part 573.6(c)(6), please amend your provided chronology to include the dates of all of the principal events that were the basis for the determination that the defect related to motor vehicle safety.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

