

**Recall Quarterly Report****18V-772**

**Manufacturer Name :** Subaru of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 18V-772 / WTY-84  
**Recall Subject :** Engine Valve Spring Failure may cause Engine Stall  
**Owner Notification Beginning Date :** DEC 26, 2018  
**Owner Notification End Date:** DEC 28, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 22, 2020	2020-1	165,534	110,514	1,481	8,007
5	JAN 29, 2020	2019-4	165,534	103,758	1,481	8,007
4	OCT 25, 2019	2019-3	165,534	93,497	1,481	8,007
3	JUL 23, 2019	2019-2	165,534	71,537	1,474	4,588
2	APR 29, 2019	2019-1	165,534	38,129	1,462	4,588
1	FEB 04, 2019	2018-4	165,534	14	0	0

This Document Last Updated : APR 24, 2020

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.