

U.S. Department of Transportation

National Highway Traffic Safety Administration

December 19, 2018

Mr. Steve Mary Winnebago Industries, Inc 605 W Crystal Lake Rd. Forest City, IA 50436 1200 New Jersey Avenue SE Washington, DC 20590

NEF-150MR 18V-855

Subject: Missing Edge Protection on Liquid Propane Lines

Dear Mr. Mary:

This letter serves to acknowledge Winnebago Industries, Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

WINNEBAGO/FORZA/2018-2019

Mfr's Report Date: November 30, 2018

NHTSA Campaign Number: 18V-855

Components:

EQUIPMENT: RECREATIONAL VEHICLE: LPG LINES AND FITTINGS

Potential Number of Units Affected: 152

Problem Description:

Winnebago Industries, Inc. (Winnebago) is recalling certain 2018-2019 Winnebago Forza motorhomes. The liquid propane (LP) lines may have been installed without edge protection where the LP lines pass through the closeout panel, possibly resulting in the lines being damaged and leaking fuel.

Consequence:

A fuel leak in the presence of an ignition source can increase the risk of a fire.

Remedy:

Winnebago will notify owners, and dealers will install edge protection at the closeout panel, free of charge. The recall is expected to begin January 18, 2019. Owners may contact Winnebago customer service at 1-641-585-6939 or 1-800-537-1885.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

The information in your report suggests that Winnebago may have been aware of this issue more than five business days before filing a report with NHTSA. Please be reminded that under Federal law, this agency is to be notified of all safety defect and/or noncompliance decisions within five business days. 49 CFR 573.6

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Kareem Habib Acting Chief, Recall Management Division Office of Defects Investigations

aslan Adul

Enforcement

