

**From:** [Broadcast Messaging System](#)  
**To:** [DL-BMS Message Monitors](#)  
**Subject:** Delivery Stop & Recall: G05 Sun Visors (11 Vehicles)  
**Date:** Friday, December 14, 2018 12:31:09 PM

Publish Date: December 14, 2018  
From: Technical Service  
Expiration Date: December 31, 2018

DCSnet Message  
**Urgent**







**Subject: Delivery Stop & Recall: G05 Sun Visors (11 Vehicles)**

BMW of North America, LLC is conducting a Voluntary Non-Compliance Recall (effective December 14, 2018) on Model Year 2019 BMW X5 SAV vehicles that have been produced from July 11 to October 30, 2018.

Attached is Service Information bulletin B51 34 18 and Recall Notice for more details.

The bulletin will be updated when additional information becomes available.

Sincerely,  
Technical Service

Attachments:  [B513418\\_Recall\\_Notice\[81d40aaa\].pdf](#)  [B513418\[81d40aa9\].pdf](#)  [B513418\\_Recall\\_Notice\[81d40aaa\].pdf](#)  
 [B513418\[81d40aa9\].pdf](#)

Recipients: All, 49134, All Departments, All Personnel  
All, 43786, All Departments, All Personnel  
All, 41518, All Departments, All Personnel  
All, 34748, All Departments, All Personnel



SI B51 34 18  
Body Equipment

December 2018  
Technical Service

---

## DELIVERY STOP & RECALL 18V-XXX: G05 SUN VISOR

### MODEL

G05 (X5)

### SITUATION

BMW of North America, LLC is conducting a Voluntary Non-Compliance Recall (effective December 14, 2018) on Model Year 2019 BMW X5 SAV vehicles that have been produced from July 11 to October 30, 2018. The driver and/or passenger sun visor air bag warning label may not meet US Federal requirements.

Approximately 11 vehicles are affected by this delivery stop/recall.

Affected vehicles show the campaign as “Open” when checked either in Warranty Vehicle Inquiry, AIR or ISPA Next and identified with the description: **STOP013511 B513418 Recall: G05 Sun Visor**

All of the other systems including DAR and the RDR system will show the Stop Sale Sign starting tomorrow. Please utilize the Inventory Campaign Details under ROSS which shows all vehicles that have a Stop Sale in your inventory.

The bulletin will be updated as soon as we have more information.

### ATTACHMENTS

View PDF attachment [B513418 Recall Notice](#).

[ Copyright ©2018 BMW of North America, Inc. ]

## **NON-COMPLIANCE RECALL NOTICE**

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Delivery Stop & Recall 18V-XXX: G05 Sun Visor (B51 34 18)

BMW of North America, LLC is conducting a Voluntary Non-Compliance Recall (effective December 14, 2018) on Model Year 2019 BMW X5 SAV vehicles that have been produced from July 11 to October 30, 2018. The driver and/or passenger sun visor air bag warning label may not meet US Federal requirements.

Owners will be notified by First Class mail about the Recall and will be instructed to bring their vehicles in for a free repair when parts are available.

**Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.**

**Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.**

**Please follow any special instructions that we provide to you for the return or disposition of recall parts.**

We appreciate all your assistance with this Recall.