

TIMING: Release on Friday, February 8th, at 2 PM

SUBJECT: IMPORTANT Information Regarding Your Indian Motorcycle

BODY:

Dear Indian Motorcycle Customer,

Our records indicate that you are the owner of a motorcycle affected by Safety Recall I-19-01 announced on February 7th, 2019. The Safety Recall specifically affects Indian Scout, Scout Sixty and Bobber models that have had the BLACK Clutch and Brake Lever accessory kit installed.

Visit our [On Road Safety Recall page](#) for more information, and to verify if your Indian Motorcycle is impacted by this recall. Your local Indian Motorcycle dealer can be found on our [Dealer Locator page](#). Contact your dealer to schedule a service appointment or complete a transfer of ownership if you no longer own the vehicle.

While your dealer is in the best position to answer your questions, you can also call our Customer Service Department at 1 (877) 204-3697 to speak with a representative.

Sincerely,

The Customer Service Team