

Part 573 Safety Recall Report

19E-019

Manufacturer Name : Ivolution Sports Inc.

Submission Date : APR 25, 2019

NHTSA Recall No. : 19E-019

Manufacturer Recall No. : HY808



Manufacturer Information :

Manufacturer Name : Ivolution Sports Inc.

Address : 1500 Commerce St.

Corona CA 92880

Company phone : 951-852-6327

Population :

Number of potentially involved : 4,761

Estimated percentage with defect : 100 %

Equipment Information :

Brand / Trade 1 : IV2

Model : HY808

Part No. : HY808

Size : S/M/L/XL/XXL

Function : head gear

Descriptive Information : In a recent test, a random selected IV2 HY808 helmet has failed impact test, however it passed other tests. The helmet may be a potential safety risk for its wearers, therefore this recall is created.

Production Dates : MAR 03, 2014 - MAR 03, 2017

Description of Noncompliance :

Description of the Noncompliance : Failed impact test.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : May not be strong enough to protect the wearer during an accident.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

Test report of the randomly selected HY808-XL helmets.

Description of Remedy :

Description of Remedy Program : Recall the products and reimburse the purchaser.
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : MAR 04, 2019 - DEC 01, 2019
Planned Owner Notification Date : MAR 04, 2019 - DEC 01, 2019

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR
Address : NR
NR
Country : NR
Company Phone : NR

* NR - Not Reported