Next Unread Message

View Message

Sent on	10 28 2019 Expires on 11 13 2019
From	Parts Operations
Subject	Monkey 125/A Accessory Rear Carrier STOP SALE Notice and Part Return Request

Honda launched a SAFETY RECALL on the Honda Genuine Accessory Rear Carrier for Monkey 125/A motorcycles due to a potential defect that may allow the Rear Carrier to fall off the motorcycle while riding. A Rear Carrier that falls into the roadway poses a safety hazard to other roadway users. All dealers with affected accessory inventory must not sell or install the affected parts. Make sure to remove the affected part number from any internet parts advertising by your dealership. Updated parts are currently not available for purchase from American Honda.

Return Request

You must return all new uninstalled PN 08L70-K0F-A00 in original packaging you have in inventory.

No Shipment Listing or Invoice is required for this return. These returns will not be charged against your SRA credit.

Return iN OAR Procedure

- 1. Complete the iN OAR procedures.
- 2. Use Reason Code "R" with eleven zeros for the Shipper Number.
- 3. Use Item Number "9999."
- 4. Enter "Monkey 125/ARear Carrier Return" in the Remarks Section.
- 5. When approved an "Authorization Return document" via the mail will be received.
- 6. Return P/N 08L70-K0F-A00 back to American Honda.

Order adjustment requests (OARs) must be submitted by 11/22/19.

If your dealership incurs freight costs for parts return, please send the following information to obtain reimbursement to ahm_inflator_swap@ahm.honda.com

- Copy of Return Authorization Form
- Copy of the freight bill
- Freight Amount
- Comments: "Requesting freight reimbursement for STOP SALE Parts"

Thank you,

American Honda Motor Co., Inc.

Parts Operations

INTERACTIVE NETWORK

NG/ms