

**Recall Quarterly Report****19E-074**

**Manufacturer Name :** Cummins Inc.  
**NHTSA Recall No. / MFR Recall No. :** 19E-074 /  
**Recall Subject :** ECM Cracked Solder Joints Can Cause Engine Stall  
**Owner Notification Beginning Date :** DEC 18, 2019  
**Owner Notification End Date:** AUG 18, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 13, 2020	2020-3	2,608	642	0	0
3	JUL 13, 2020	2020-2	2,608	591	0	0
2	APR 21, 2020	2020-1	2,608	504	0	0
1	JAN 31, 2020	2019-4	2,608	320	0	0

This Document Last Updated : OCT 14, 2020

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.