OMB Control No.: 2127-0004

Recall Quarterly Report

19V-008

Manufacturer Name: Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 19V-008 /TKB-19

Recall Subject: Passenger Frontal Air Bag Inflator May Explode

Owner Notification Beginning Date: JAN 25, 2019

Owner Notification End Date: MAR 08, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JUL 05, 2019	2019-2	330,120	155,519	0	11,047
1	APR 15, 2019	2019-1	330,120	73,921	0	10,604

This Document Last Updated: AUG 01, 2019

Definitions:

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the $3^{\rm rd}$ quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.