Recall Quarterly Report

19V-040

Manufacturer Name : Jaguar Land Rover North America, LLC NHTSA Recall No. / MFR Recall No. : 19V-040 /N276 Recall Subject : Crankshaft Pulley Bolt May Fracture Owner Notification Beginning Date : FEB 12, 2019 Owner Notification End Date: FEB 12, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JUL 23, 2019	2019-2	2,587	2,176	7	0
1	APR 29, 2019	2019-1	2,587	2,006	4	0

This Document Last Updated : JUL 29, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7