OMB Control No.: 2127-0004

Recall Quarterly Report

19V-059

Manufacturer Name: Gillig LLC

NHTSA Recall No. / MFR Recall No.: 19V-059 / **Recall Subject:** Ball Stud Improperly Torqued **Owner Notification Beginning Date: MAR 20, 2019**

Owner Notification End Date: MAR 20, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 17, 2019	2019-3	3,659	2,339	0	0
2	JUN 26, 2019	2019-2	3,659	1,813	0	0
1	APR 08, 2019	2019-1	3,659	129	0	0

This Document Last Updated: OCT 21, 2019

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.