

Part 573 Safety Recall Report

19V-085

Manufacturer Name : Forest River, Inc.**Submission Date :** FEB 08, 2019**NHTSA Recall No. :** 19V-085**Manufacturer Recall No. :** 64-0948**Manufacturer Information :****Population :**

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 10

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1 : 2019-2019 Forest River, Inc. Cherokee - CKT18TO-OR & CST18TOC-OR

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : On January 31, 2019, the Cherokee plant discovered that the Federal Placard had incorrect tire information. Using the production schedule records, Cherokee was able to determine the affected vehicles.

CKT18TO-OR - 1

CST18TOC-OR - 9

Production Dates : JAN 22, 2019 - JAN 23, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Noncompliance :**

Description of the Noncompliance : The subject vehicles' Federal Placards indicate an incorrect Tire. The Federal Placard indicates ST205/75R15/E Tires with 80 PSI. The subject vehicles received ST225/75R15/E Tires with 80 PSI.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : 567 - Certification

Description of the Safety Risk : An operator may install a tire that is not sufficient for the vehicle.

Description of the Cause : The incorrect tire package was selected which led to incorrect information being printed on the Federal Placards.

Identification of Any Warning that can Occur : None

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On January 31, 2019 Forest River's Cherokee manufacturing plant alerted Forest River's OCC to an issue with the FED Tag having incorrect tire information listed. On February 4, 2019, an investigation was opened, a scope of VINs were determined by production records that reflect the production of the affected vehicles. On February 8th, 2019 Forest Rivers Corporate Recall Committee voted to recall.

Description of Remedy :

Description of Remedy Program : Forest River will provide the Owner and Dealer of current record with the new Federal Placard for installation, free of charge.

What is the Forest River Customer Service Phone Number? (541)
644-8072 x 4022

How Remedy Component Differs from Recalled Component : The new Federal Placard will indicate the correct tire and PSI.

Identify How/When Recall Condition was Corrected in Production : The issue was corrected in manufacturing the week of January 31, 2019.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : MAR 20, 2019 - MAR 20, 2019

Planned Owner Notification Date : MAR 20, 2019 - MAR 20, 2019

* NR - Not Reported