

Part 573 Safety Recall Report

19V-090

Manufacturer Name : Ferrari North America, Inc.**Submission Date :** FEB 14, 2019**NHTSA Recall No. :** 19V-090**Manufacturer Recall No. :** 69**Manufacturer Information :**

Manufacturer Name : Ferrari North America, Inc.

Address : 250 Sylvan Avenue

Englewood Cliffs NJ 07632-2500

Company phone : 1800-999-9999

Population :

Number of potentially involved : 2,150

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2018-2019 Ferrari 488 GTB

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All vehicles in the production range.

Production Dates : OCT 31, 2017 - OCT 11, 2018

VIN Range 1 : Begin : ZFF79ALAXJ0231425 End : ZFF79ALA7K0240861 Not sequential

Vehicle 2 : 2018-2019 Ferrari GTC4Lusso T

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All vehicles in the production range.

Production Dates : OCT 31, 2017 - OCT 18, 2018

VIN Range 1 : Begin : ZFF82YNA6J0230951 End : ZFF82YNA9K0240908 Not sequential

Vehicle 3 : 2018-2019 Ferrari GTC4Lusso

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All vehicles in the production range.

Production Dates : OCT 31, 2017 - OCT 22, 2018

VIN Range 1 : Begin : ZFF82WNA9J0231788 End : ZFF82WNAXK0241327 Not sequential

Vehicle 4 : 2018-2019 Ferrari 488 Spider

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All vehicles in the production range.

Production Dates : OCT 31, 2017 - OCT 22, 2018

VIN Range 1 : Begin : ZFF80AMA1J0231665 End : ZFF80AMA4K0240880 Not sequential

Vehicle 5 : 2019-2019 Ferrari 488 Pista

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All vehicles in the production range.

Production Dates : JUL 23, 2018 - OCT 19, 2018

VIN Range 1 : Begin : ZFF90HLA0K0239417 End : ZFF90HLA8K0241447 Not sequential

Vehicle 6 : 2018-2019 Ferrari 812 Superfast

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All vehicles in the production range.

Production Dates : NOV 02, 2017 - OCT 22, 2018

VIN Range 1 : Begin : ZFF83CLA6J0230242 End : ZFF83CLA2K0241501 Not sequential

Vehicle 7 : 2017-2017 Ferrari LaFerrari Aperta

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All vehicles in the production range.

Production Dates : OCT 31, 2017 - DEC 05, 2017

VIN Range 1 : Begin : ZFF86ZHA7H0231364 End : ZFF86ZHA0H0232856 Not sequential

Description of Defect :

Description of the Defect : The vehicles involved are equipped with a fuel vapor separator which, due to a manufacturing fault caused by the supplier, may cause the fuel to evaporate and the vehicle to ignite.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The defect may cause a potential fuel vapor leak and/or fire.

Description of the Cause : The plastic weld in the Fuel Vapor Separator may crack due to the manufacturing process.

Identification of Any Warning that can Occur : The Check Engine warning light will illuminate & show a message instructing the owner to take the vehicle to the dealer.

Supplier Identification :**Component Manufacturer**

Name : Sumiriko Italy S.p.A.
Address : Via Andrea Doria 15
Torino FOREIGN STATES 10123
Country : Italy

Chronology :

Ferrari had reports of the issue from the Authorized Dealer Network. After a thorough investigation Ferrari determined that the leakage was caused by a fault in the manufacturing process of the component.

Description of Remedy :

Description of Remedy Program : Ferrari will replace the fuel vapor separator, free of charge.
How Remedy Component Differs from Recalled Component : The correct component is identified with a label (not present in the defective components) and through specific production date of each batch to guarantee the traceability.
Identify How/When Recall Condition was Corrected in Production : The defect was corrected by the supplier & implemented on the assembly line, starting with VIN # ZFF89FPA3K0241176.

Recall Schedule :

Description of Recall Schedule : Ferrari will begin notifying customers in April 2019.
Planned Dealer Notification Date : APR 14, 2019 - NR
Planned Owner Notification Date : APR 14, 2019 - NR

* NR - Not Reported