

IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s) with the VIN(s) indicated on the enclosed owner response cards.

AUTOCAR, LLC SAFETY RECALL ACX-1903 NHTSA RECALL NO. 19V091 April 2019

Dear Autocar Truck Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect which relates to motor vehicle safety exists in 260, 2008 to 2019 model year Xpeditor chassis. These chassis were manufactured between April 18, 2008 and January 26, 2019 with non-sequential serial numbers in the range 207650 through 230313. Our records indicate that your vehicle was manufactured within this time-period and may contain the defect described herein.

MODELS Autocar Xpeditor 2008 to 2019

AFFECTED:

AFFECTED:

COMPONENTS Parking brake chambers.

SAFETY DEFECTS

AND POTENTIAL RISKS:

The parking brake chambers originally installed are not large enough to hold the fully laden vehicle stationary while parked on an incline, increasing the risk of a roll away condition, which can increase the risk of a crash, personal injury or property damage.

REPAIR REQUIRED:

The parking brake chambers will be replaced with the correct size parking brake chambers.

TIME REQUIRED FOR THE REPAIR:

The labor time to repair your vehicle is 2.0 hours.

WHAT YOU SHOULD DO: To have your vehicle repaired, contact your local authorized Autocar service site or email warranty@autocartruck.com.

PRIOR REPAIRS:

If you have previously paid for repairs relating to this recall you may be entitled to recover the amount you paid for those repairs. Submit a copy of all documentation supporting your claim to Autocar at the address set forth below in the "Assistance" section.

ACF 00002 Rev. 000



NOTICE REGARDING LEASED VEHICLES:

If you are a Lessor (as defined below) of a vehicle that is affected by this Notice, you are obligated under federal law to provide a copy of this Notice to the Lessee of such vehicle within 10 days of your receipt of this Notice. Further, you must maintain a record, which identifies the Lessee(s) to whom you send a copy of this Notice, the date you send the Notice and the VIN of the vehicle that you have leased to the Lessee(s).

For purposes of this Notice, the term "Lessor" means a person or entity that is the owner, as reflected on the vehicle's title, of any five or more leased vehicles as of the date of this Notice.

OWNER RECALL RESPONSE CARD:

The enclosed Owner Recall Response Card identifies your vehicle. Please complete this postage-paid card and return it to Autocar. If you do not own, have sold, or have traded the vehicle identified on the card, please indicate that on the postage-paid card and return it to Autocar.

ASSISTANCE:

If you need assistance with this recall, call our toll-free numbers below or write to Autocar at:

Autocar, LLC Service & Warranty Departments 551 S. Washington St. Hagerstown, IN 47346 888-218-3611 (Toll Free) 877-973-3486 (Toll Free)

You may also submit a complaint to:

Administrator National Highway Traffic Safety Administration 1200 New Jersey Avenue SE Washington, DC 20590

Or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 800-424-9153); or go to http://www.safercar.gov.

We regret any inconvenience this recall may cause, but we hope you recognize Autocar's concern for your safety and satisfaction with your vehicle.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000