

U.S. Department of Transportation

# National Highway Traffic Safety Administration

March 28, 2019

Mr. Greg Gunther
Department Manager VCA
Mercedes-Benz USA, LLC.
13470 International Parkway

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Incorrect Rear Seat Back Covering/FMVSS 225

Dear Mr. Gunther:

Jacksonville, FL 32218

This letter serves to acknowledge Mercedes-Benz USA, LLC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

#### Makes/Models/Model Years:

MERCEDES BENZ/GLA250/2018-2019

Mfr's Report Date: February 26, 2019

NHTSA Campaign Number: 19V-132

**Components:** 

**SEATS** 

**Potential Number of Units Affected:** 8

#### **Problem Description:**

Mercedes-Benz USA, LLC (Mercedes) is recalling certain 2018-2019 GLA-250 and GLA250 4MATIC vehicles. An incorrect rear seat back covering carpet could have been installed on the split-rear seat back. As a result, the child seat anchorage point (top tether) on the center position of the rear seat may be covered and inaccessible for use. As such, these vehicles fail to comply to Federal Motor Safety Standard (FMVSS) number 225, "Child Restraint Anchorage Systems."

## **Consequence:**

If the upper anchorage point is covered, the child seat will not be able to be secured as intended in the center position of the rear seat, increasing the risk of injury in the event of a crash.

### Remedy:

Mercedes will notify owners, and dealers will check the rear seat back covering carpet on the affected vehicles and replace it if necessary, free of charge. The recall is expected to begin April 26, 2019. Owners may contact Mercedes-Benz's customer service at 1-800-367-6372. Mercedes' number for this recall is 2019030003.

## **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

The information in your report suggests that Mercedes-Benz may have been aware of this issue more than five business days before filing a report with NHTSA. Please be reminded that under Federal law, this agency is to be notified of all safety defect and/or noncompliance decisions within five business days. 49 CFR 573.6 Significant civil penalties can be assessed for this violation.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,

Kareem Habib

Acting Chief, Recall Management Division

aslan Adulas

Office of Defects Investigations

Enforcement

