

Recall Quarterly Report**19V-152**

Manufacturer Name : Terex Advance Mixer, Inc.
NHTSA Recall No. / MFR Recall No. : 19V-152 /
Recall Subject : Caliper Drive Pins may Fracture
Owner Notification Beginning Date : APR 23, 2019
Owner Notification End Date: APR 23, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	NOV 11, 2019	2019-3	98	51	0	0
1	AUG 05, 2019	2019-2	98	42	0	0

This Document Last Updated : NOV 12, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.