OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 19V-175

Manufacturer Name: Entegra Coach
Submission Date: MAR 05, 2019
NHTSA Recall No.: 19V-175
Manufacturer Recall No.: 9903428



#### **Manufacturer Information:**

Population :

Manufacturer Name: Entegra Coach

Number of potentially involved: 23

Address: 903 South Main Street

Estimated percentage with defect: 100 %

P.O. Box 460 Middlebury IN 46540

Company phone: 1-800-945-4787

#### **Vehicle Information:**

Vehicle 1: 2019-2019 Entegra Class C MH Esteem Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: Supplier POs delivered substitue brake cable - matched to production records for

affected unit serial numbers

2019 Entegra Esteem K1BF8061-8068 BV8162-8169 BX8119-8125

Production Dates: JAN 15, 2019 - FEB 06, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

#### **Description of Defect:**

Description of the Defect: End of the parking brake cable are too small and could pull out from the

retaining slipo, casuing emergency brake to not engage. Failure is not

immediate, partk brake could fail after several engagments, Subsitued cabel

was not inpsected nor tested to FMVSS 49CFR571.105 by supplier

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: IF the park brake does not engage, the vehicle may not stay stationary as

required on an incline. This could result in prsonal injury and/or property

damage.

Description of the Cause: L & W made a substitution to the brake cable - - jayco was not made aware of

the substitution - The configuration of the ends of the substitued cables are

smaller.

Identification of Any Warning NR

that can Occur:

## **Supplier Identification:**

## **Component Manufacturer**

Name: L & W Engineering

Address: 107 Industrial Parkway

Middlebury INDIANA 46540

Country: United States

#### **Chronology:**

2-2019 during normal line audit of ebrakes - production noted numerours failures - ebrake did not engage 2-5-19 Supplier, L & W was made aware of incidents - research started immediately. L&W responded that a substitut ion cable was dleivered to production - production stopped immediately installing the park brake - 2-14-19 Jayco met with L&W to discuss specifics and to address changing a component on a regulatory system without validation. 2-28-19 Safety Committee discussed details of incident and agrred that recall is required.

## **Description of Remedy:**

Description of Remedy Program : REmove and repalce the parking brake cable

How Remedy Component Differs Correct brake cable part # 0299065

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: Entegra is ready to release recall upon reciepot of recall number assigned

by NHTSA

Planned Dealer Notification Date : MAR 29, 2019 - MAR 29, 2019 Planned Owner Notification Date : MAR 29, 2019 - MAR 29, 2019

\* NR - Not Reported