



IMPORTANT SAFETY RECALL

AUTOCAR, LLC SAFETY RECALL ACX-1904
NHTSA RECALL NO. 19V227
TC RECALL NO. 2019212
May, 2019

TO: U.S. and Canadian Distributors
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect which relates to motor vehicle safety exists in 656, 2019-2020 model year Xpeditor chassis. These chassis were manufactured between March 6, 2018 and March 1, 2019 with non-sequential serial numbers in the range 227072 through 230678. Accordingly, a recall to address this issue is being initiated effective May 21, 2019.

MODELS Autocar Xpeditor MY 2019-2020
AFFECTED:

COMPONENTS Brake Chamber hardware (clevis pins).
AFFECTED:

SAFETY DEFECTS The brake chamber clevis pin(s) may not be installed. If the clevis pin(s) are not installed
AND POTENTIAL the vehicle would experience increased stopping distances, increasing the risk of a
RISKS: crash, personal injury or property damage.

REPAIR The brake chambers hardware will be inspected and repaired or replaced as required.
REQUIRED:

REPAIR VIN profiles in the Autocar Warranty System will be updated to show the open recall on
AVAILABLE: May 21, 2019 and a spreadsheet of the affected VINs will be available in the Warranty system.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at warranty@autocartruck.com.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000