

U.S. Department of Transportation

# National Highway Traffic Safety Administration

May 15, 2019

Mr. Tim LaFon
Nova Bus
1000 Industriel Blvd.
Saint-Eustache J7R 5A5

NEF-150MR
19V-274

Subject: Engine Door Fan Connector may Overheat

Dear Mr. LaFon:

This letter serves to acknowledge Nova Bus's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

#### Makes/Models/Model Years:

NOVA BUS/LFS/2011-2019

Mfr's Report Date: April 5, 2019

NHTSA Campaign Number: 19V-274

## **Components:**

**ELECTRICAL SYSTEM** 

Potential Number of Units Affected: 1,500

## **Problem Description:**

Nova Bus (Nova) is recalling certain 2011-2019 LFS city buses. The engine door fan electrical connector may not be able to handle the required current and may overheat, possibly resulting in a fire.

# **Consequence:**

A vehicle fire increases the risk of injury.

#### Remedy:

Nova will notify owners, and dealers will replace the connector, free of charge. The recall is expected to begin on May 23, 2019. Owners may contact Nova customer service at 1-800-350-6682. Nova's number for this recall is CR4595.

#### Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to Nova instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Kareem Habib Acting Chief, Recall Management Division Office of Defects Investigations

aslow Adds

Enforcement

