

**Recall Quarterly Report****19V-297**

**Manufacturer Name :** Subaru of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 19V-297 /WUF-91  
**Recall Subject :** Ignition Switch may Turn Off  
**Owner Notification Beginning Date :** MAY 10, 2019  
**Owner Notification End Date:** MAY 10, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 05, 2019	2019-2	511	119	1	12

This Document Last Updated : AUG 01, 2019

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.