

Recall Quarterly Report

19V-314

Manufacturer Name : Mercedes-Benz USA, LLC.

NHTSA Recall No. / MFR Recall No. : 19V-314 / 2019050002

Recall Subject : Pedal Plate May Bend, Impairing Brake Pedal Use

Owner Notification Beginning Date : MAY 31, 2019

Owner Notification End Date: MAY 31, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	OCT 07, 2019	2019-3	1,051	747	0	0
1	JUL 15, 2019	2019-2	1,051	526	0	0

This Document Last Updated : NOV 15, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.