

**List of Body Builders involved in FL814 Recall**

CAMBLI INTERNATIONAL INC.

HI V COMPANY

INTERCONTINENTAL TRUCK BODY

MORGAN OLSON

UTILIMASTER

# Daimler Trucks North America LLC

Daimler Trucks North America LLC  
P.O. Box 4090  
Portland, OR 97208-4090  
800.547.0712 Phone  
503.745.9009 Fax

July 2019  
FL814A-C  
Interim Recall Notice  
NHTSA #19V-371

## IMPORTANT SAFETY RECALL This notice applies to your vehicle(s)

### Subject: FCCC MT Chassis Brake Pedal Clevis Pins

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler Trucks North America LLC (DTNA), on behalf of its wholly-owned subsidiary Freightliner Custom Chassis Corporation, has decided that a defect that relates to motor vehicle safety exists on specific Freightliner Custom Chassis MT45 and MT55 step vans, manufactured January 12, 2011, through January 3, 2019.

The clearance between the brake pedal clevis pin clip and the throttle pedal mounting hardware does not meet minimum clearance requirements. This could result in detachment of the brake pedal clevis pin clip. As the clevis pin works out, there will initially be loss of brake lights, and eventually the brake pedal may become detached. Both the loss of brake lights and a detached brake pedal increase the risk of a crash.

This is the first of two notices you will receive regarding this subject. This letter is to inform you of an upcoming Recall to correct the issue noted above. Daimler Trucks is currently securing replacement parts. There is no action for you to take at this time.

The second notice will inform you when the final remedy is available. **When you receive the second notice**, please contact your authorized Daimler Trucks North America dealer to schedule the Recall for your vehicle.

If you do not own the vehicle that corresponds to the identification number(s), which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com, or the Customer Assistance Center at (800) FTL-HELP after normal business hours. If you are not able to have the defect remedied without charge and within a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT  
Enclosure