

U.S. Department of Transportation

National Highway Traffic Safety Administration

June 24, 2019

Mr. Chris Sandvig Volkswagen Group of America, Inc. 3800 Hamlin Road Auburn Hills, MI 48326 1200 New Jersey Avenue SE Washington, DC 20590

NEF-150SS 19V-385

Subject: No Indicator For Failed Turn Signal

Dear Mr. Sandvig:

This letter serves to acknowledge Volkswagen Group of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

AUDI/Q3/2016-2018

Mfr's Report Date: May 23, 2019

NHTSA Campaign Number: 19V-385

Components:

EXTERIOR LIGHTING:TURN SIGNAL

Potential Number of Units Affected: 23,241

Problem Description:

Volkswagen Group of America, Inc. (Audi) is recalling certain 2016-2018 Audi Q3 vehicles equipped with LED headlights. An inoperable front turn signal may not illuminate an indicator, failing to alert the driver to the issue. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence:

Without an indicator informing the driver of an inoperable turn signal, the driver may turn or change lanes without a signal, increasing the risk of crash.

Remedy:

Audi will notify owners, and dealers will update the body control module (BCM), free of charge. The recall is expected to begin July 19, 2019. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 97DK.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received Audi's proposed owner notification letter and approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Shiver who may be reached by phone at (202) 366-7401, or by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff

Acting Chief, Recall Management Division

Office of Defects Investigations

Enforcement

