



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 24, 2019

Ms. Alexa Sacco
LGE Coachworks Inc.
10190 West Main Road
Suite 102
North East, PA 16428

NEF-150MR
19V-398

Subject: Back Up Camera Display Image may be Reversed

Dear Ms. Sacco:

This letter serves to acknowledge LGE Coachworks Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FORD/F-450/2018-2019
FORD/F-550/2018-2019
FREIGHTLINER/BUSINESS CLASS M2/2018-2019

Mfr's Report Date: May 29, 2019

NHTSA Campaign Number: 19V-398

Components:

EQUIPMENT

Potential Number of Units Affected: 13

Problem Description:

LGE Coachworks, Inc. (LGE Coachworks) is recalling certain 2018-2019 Ford E-450, F-550, and Freightliner M2-based vehicles equipped with ASA Electronics Voyager back-up camera displays. The displays may unexpectedly revert back to the factory default settings which may cause the camera image to be reversed.

Consequence:

The driver may inadvertently turn the wrong direction to avoid an object behind the vehicle, increasing the risk of a crash.

Remedy:

ASA will notify LGE Coachworks owners, and dealers will replace the displays, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact ASA customer service at 1-800-384-4400 or LGE Coachworks at 1-800-209-3985.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

By regulation, LGE Coachworks is required to notify their customers by first class mail on LGE Coachworks letterhead.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Acting Chief, Recall Management Division
Office of Defects Investigations
Enforcement