



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 20, 2019

Ms. Celina Tyler
Consumer Affairs Manager
Thor Motor Coach
P. O. Box 1486
Elkhart, IN 46515

NEF-150KL
19V-417

Subject: Extra Screw in Junction Box May Cause Fire

Dear Ms. Tyler:

This letter serves to acknowledge Thor Motor Coach's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

THOR/MAGNITUDE/2019-2020
THOR/OMNI/2019-2020

Mfr's Report Date: June 5, 2019

NHTSA Campaign Number: 19V-417

Components:

ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 81

Problem Description:

Thor Motor Coach (TMC) is recalling certain 2019-2020 Magnitude, Omni motorhomes, models BB35 and BH35. Wires located in the electrical junction box may move around and contact an extra screw that was errantly installed.

Consequence:

Contact with the screw may result in the wiring insulation being damaged, increasing the risk of an electrical short circuit and a fire.

Remedy:

TMC will notify owners, and dealers will inspect the junction box and remove the extra screw, and repair any damaged wiring, as necessary, free of charge. The recall is expected to begin August 5, 2019. Owners may contact TMC customer service at 1-877-855-2867. TMC's number for this recall is RC000169.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received TMC's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:


Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kristin Lepper who may be reached by phone at 202-366-5227, or by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Acting Chief, Recall Management Division
Office of Defects Investigations
Enforcement