## **Recall Quarterly Report**

19V-417

Manufacturer Name : Thor Motor Coach NHTSA Recall No. / MFR Recall No. : 19V-417 /RC000169 Recall Subject : Extra Screw in Junction Box May Cause Fire Owner Notification Beginning Date : JUL 15, 2019 Owner Notification End Date: JUL 15, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 17, 2020	2019-4	81	58	0	0
1	OCT 30, 2019	2019-3	81	50	0	0

This Document Last Updated : JAN 17, 2020

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7