

July 9, 2019

Mr. James Hurst Product Safety Engineer Vac-Tron Equipment, LLC 27137 South Hwy 33 Okahumpka, FL 34762

Subject: Missing Lamps and Reflective Tape

Dear Mr. Hurst:

This letter serves to acknowledge Vac-Tron Equipment, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: VAC-TRON/LP 873 SD/2015-2019

Mfr's Report Date: June 11, 2019

NHTSA Campaign Number: 19V-442

Components: EXTERIOR LIGHTING

Potential Number of Units Affected: 208

Problem Description:

Vac-Tron Equipment, LLC. (Vac-Tron) is recalling certain 2015-2019 LP873SDT Heavy, Vacuum Excavator-dual axle trailers. The trailer may lack front and rear lights, including clearance lamps, reflex reflectors, and side reflex reflectors. The trailers may also may have an insufficient amount of reflective tape on the sides and rear. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence:

Due to the lack of lamps and insufficient reflective tape, the trailer may not be visible at night, increasing the risk of crash.

Remedy:

The remedy for this recall is still under development. The manufacturer has not yet provided a notification schedule. Owners may contact Vac-Tron customer service at 1-888-822-8766.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

Image: Constraint of the second se

1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 19V-442

- A description of how the products to be recalled differ from similar products that are not included in the recall (49 CFR 573.6 (c) (2)).

- A statement that the defect or noncompliance can cause a vehicle crash. (49 CFR 577.5 (f)(1)).

- A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

- Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefore, and furnish a revised estimate (49 CFR 573.6 (c)(8)(ii)).

- Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefore, and furnish a revised estimate. (49 CFR 573.6 (c)(8)(ii)).

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Acting Chief, Recall Management Division Office of Defects Investigations Enforcement

