

Recall Quarterly Report**19V-493**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 19V-493 /WUH-93
Recall Subject : Improperly Applied Spot Welds
Owner Notification Beginning Date : JUL 26, 2019
Owner Notification End Date: JUL 26, 2019



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 1 | OCT 25, 2019 | 2019-3 | 2,107 | 2,099 | 0 | 0 |

This Document Last Updated : OCT 25, 2019

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.