



Uptime

Recall Alerts

To: U.S. and Canada Distributors
Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Region: U.S.
 CAN

Bulletin: SRA-V19-03

Date: July 12, 2019

Valid to: N/A

Action Required? Yes No

From: Gerard Honas, Regulatory Specialist Government Reporting
Subject: Safety Recall RVXX1903, I-Shift Transmission ECU Fuse

Description of Defect:

On certain vehicles, the fuse used in a transmission circuit has a rating that is lower than what is required. As a result, the fuse can open under normal operating conditions and cause the transmission to not shift. This does not affect the brake system; however, under certain conditions this may contribute to a vehicle crash.

Models/ Model Years Affected:

Volvo: Certain 2018-2020 VAH, VHD, VNL and VNM models manufactured from June 13, 2017 through March 28, 2019

Vehicle Quantities:

Volvo: Approximately 530 vehicles (235 in the U.S., 265 in Canada and 30 in Mexico).

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle list will be posted on the Trucks Dealer Portal July 12, 2019.
- Owner notification letters will be released on or before August 19, 2019.

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.