

**Recall Quarterly Report****19V-625****Manufacturer Name :** Jayco, Inc.**NHTSA Recall No. / MFR Recall No. :** 19V-625 /9901434**Recall Subject :** Steering Shaft Bolts may be Improperly Tightened**Owner Notification Beginning Date :** SEP 23, 2019**Owner Notification End Date:** SEP 23, 2019

| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2        | DEC 23, 2019    | 2019-4         | 14                | 6              | 0                 | 0             |
| 1        | OCT 30, 2019    | 2019-3         | 14                | 2              | 0                 | 0             |

This Document Last Updated : DEC 26, 2019

**Definitions :**Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.