OMB Control No.: 2127-0004

Recall Quarterly Report

19V-664

Manufacturer Name: Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 19V-664 /WUL-97

Recall Subject: Loose or Missing Brake Pedal Mounting Bracket Bolt

Owner Notification Beginning Date: OCT 01, 2019

Owner Notification End Date: OCT 01, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 23, 2020	2020-2	3,467	3,459	0	0
2	APR 13, 2020	2020-1	3,467	3,458	0	0
1	JAN 21, 2020	2019-4	3,467	3,448	0	0

This Document Last Updated: JUL 24, 2020

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.