



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

October 7, 2019

Mr. Charlie Grimes  
Warranty Advisor  
Ferrara Fire Apparatus, Inc.  
27855 James Chapel Rd.  
Holden, LA 70744

NEF-150MR  
19V-677

**Subject:** Loss of Hydraulic Steering Assist

Dear Mr. Grimes:

This letter serves to acknowledge Ferrara Fire Apparatus, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

FERRARA/INFERNO/2015-2019

**Mfr's Report Date:** September 24, 2019

**NHTSA Campaign Number:** 19V-677

**Components:**

SUSPENSION:FRONT

**Potential Number of Units Affected:** 25

**Problem Description:**

Ferrara Fire Apparatus, Inc. (Ferrara) is recalling certain 2015-2019 Inferno fire trucks equipped with independent front suspensions manufactured by Reyco Granning. The front shocks may separate from their upper mount on the front suspension. The loose shock may contact and damage the steering gear housing, possibly causing a steering fluid leak and a loss of power steering assist.

**Consequence:**

A loss of hydraulic steering assist can increase the risk of a crash.

**Remedy:**

Ferrara will notify owners and will work with Reyco Granning to inspect and remedy the vehicles free of charge. The recall is expected to begin October 28, 2019. Owners may contact Ferrara customer service at 1-800-443-9006.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

We have received Ferrara's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)).
- In the case of a defect, a chronology of all principal events that were the basis for the determination that the defect related to motor vehicle safety, including a summary of all warranty claims, field or service reports, and other information (such as numbers of deaths and/or injuries), with their dates of receipt (49 CFR 573.6 (c)(6)).
- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

Please be reminded of the following requirements:


Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at [michelle.rice@dot.gov](mailto:michelle.rice@dot.gov). We look forward to working with you.

Sincerely,



Joshua Neff  
Chief, Recall Management Division  
Office of Defects Investigations  
Enforcement