



RECALL CAMPAIGN BULLETIN

Classification: BR19-005d	Reference: NTB19-103d	Date: September 10, 2020
------------------------------	--------------------------	-----------------------------

VOLUNTARY SAFETY RECALL CAMPAIGN 2016-2018 MAXIMA, 2015-2018 MURANO AND 2017-2019 PATHFINDER; ABS ACTUATOR INSPECTION

CAMPAIGN ID #: R1916
APPLIED VEHICLES: 2016-2018 Maxima (A36)
2015-2018 Murano (Z52)
2017-2019 Pathfinder (R52)

This bulletin has been superseded by NTB19-104.

Please discard previous versions of this bulletin.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 12, 2019	NTB19-103	Original bulletin published
November 13, 2019	NTB19-103a	Email address changed on page 3
December 17, 2019	NTB19-103b	Additional information added to the body of the bulletin
February 4, 2020	NTB19-103c	Information revised in step 4 on page 4
September 10, 2020	NTB19-103d	Bulletin superseded

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.