

December 11, 2019

Mr. Michael Nixdorf Director, Product Integrity Harley-Davidson Motor Company 11800 W. Capitol Drive Wauwatosa, WI 53222

Subject: Unintended Activation of One Rear Brake

Dear Mr. Nixdorf:

This letter serves to acknowledge Harley-Davidson Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HARLEY-DAVIDSON/FLHTCUTG/2019-2020 HARLEY-DAVIDSON/FLHTCUTGSE/2019-2020 HARLEY-DAVIDSON/FLRT/2019-2020

Mfr's Report Date: November 22, 2019

NHTSA Campaign Number: 19V-843

Components: TRACTION CONTROL SYSTEM

Potential Number of Units Affected: 12,624

Problem Description:

Harley-Davidson Motor Company (Harley-Davidson) is recalling certain 2019-2020 FLHTCUTG, FLRT, and FLHTCUTGSE Trike motorcycles. The Trike Traction Control System software may respond incorrectly to a faulty rear wheel speed signal by activating one of the rear brakes.

Consequence:

Unintended activation of one rear brake could lead to an unexpected change in vehicle direction which may increase the risk of a crash.

Remedy:

Harley-Davidson has notified owners, and dealers will update the traction control system software, free of charge. The recall began December 2, 2019. Owners may contact Harley-Davidson customer service at 1-800-258-2464. Harley-Davidson's number for this recall is 0175.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150DM 19V-843



Please be reminded of the following requirements:

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be DeMara Magruder who may be reached by phone at (202) 366-8538, or by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

