Manufacturer Name :Porsche Cars North America, Inc.Submission Date :DEC 11, 2019NHTSA Recall No. :19V-875Manufacturer Recall No. :AKCO

Manufacturer Information :

Manufacturer Name : Porsche Cars North America, Inc. Address : One Porsche Drive Atlanta GA 30354 Company phone : 1-800-767-7243

Vehicle Information :

Vehicle 1:	2014-2014 Porsche Cayman
Vehicle Type :	LIGHT VEHICLES
Body Style :	2-DOOR
Power Train :	GAS
Descriptive Information :	The recall population was determined based on review of Child Restraint System CRS installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions in the owner's manuals.
Production Dates :	NOV 16, 2012 - MAY 23, 2014
VIN Range 1:	Begin: WP0CA2A87EK170006 End: WP0AA2A85EK174806 🗸 Not sequential
Vehicle 2:	2014-2014 Porsche Cayman S
	LIGHT VEHICLES
Body Style :	2-DOOR
Power Train :	GAS
Descriptive Information :	The recall population was determined based on review of Child Restraint System CRS installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions in the owner's manuals.
Production Dates :	FEB 08, 2013 - MAY 23, 2014
VIN Range 1 : Begin : WP0AB2A84EK190024 End : WP0AB2A82EK193889 Not sequential	
Vehicle 3:	2014-2014 Porsche 911 GT3
Vehicle Type :	LIGHT VEHICLES
Body Style :	
The ir	formation contained in this report was submitted pursuant to 49 CFR §573

 Image: Constraint of the second system

 Image: Constraint of the second system

 Image: Constraint of the second system

19V-875



Population :

Number of potentially involved : 15,501 Estimated percentage with defect : 100 %

Page 2

Power Train :	GAS
Descriptive Information :	The recall population was determined based on review of Child Restraint System CR installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions the owner's manuals.
Production Dates :	OCT 19, 2013 - SEP 24, 2014
VIN Range 1:	Begin : WP0AC2A9XES183066 End : WP0AC2A96ES183677 🗸 Not sequentia
Vehicle 4:	2015-2015 Porsche 911 GT3
Vehicle Type :	LIGHT VEHICLES
Body Style :	
Power Train :	
Descriptive Information :	The recall population was determined based on review of Child Restraint System CR installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions the owner's manuals.
Production Dates :	AUG 26, 2014 - JUN 16, 2015
	Begin : WP0AC2A96FS183101 End : WP0AC2A97FS189263 🗸 Not sequentia
Vehicle 5 :	2016-2016 Porsche 911 GT3
	LIGHT VEHICLES
Body Style :	
Power Train :	
Descriptive Information :	The recall population was determined based on review of Child Restraint System CR installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions the owner's manuals.
Production Dates ·	MAY 29, 2015 - JAN 11, 2016
	Begin : WP0AC2A93GS184062 End : WP0AC2A91GS184271 Not sequentia
Vehicle 6:	2016-2016 Porsche 911 GT3 RS
	LIGHT VEHICLES
Body Style :	
Power Train :	
	The recall population was determined based on review of Child Restraint System CR installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions

the owner's manuals. Production Dates : MAY 27, 2015 - DEC 23, 2016 VIN Range 1: Begin: WP0AF2A91GS187064 End: WP0AF2A92GS193911 \checkmark Not sequential Vehicle 7: 2018-2018 Porsche 911 GT3 Vehicle Type : LIGHT VEHICLES Body Style: 2-DOOR Power Train: GAS Descriptive Information : The recall population was determined based on review of Child Restraint System CRS installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions in the owner's manuals. Production Dates : AUG 30, 2017 - DEC 21, 2018 VIN Range 1 : Begin : WP0AC2A94JS174065 End : WP0AC2A97JS177204 \checkmark Not sequential Vehicle 8: 2016-2016 Porsche 911 R Vehicle Type : LIGHT VEHICLES Body Style: 2-DOOR Power Train : GAS Descriptive Information : The recall population was determined based on review of Child Restraint System CRS installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions in the owner's manuals. Production Dates : JUN 28, 2016 - DEC 23, 2016 VIN Range 1: Begin: WP0AF2A94GS195062 End: WP0AF2A92GS195383 \checkmark Not sequential Vehicle 9: 2018-2018 Porsche 911 GT2 RS Vehicle Type : LIGHT VEHICLES Body Style: 2-DOOR Power Train: GAS

Descriptive Information : The recall population was determined based on review of Child Restraint System CRS installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions in the owner's manuals.

Production Dates : FEB 09, 2018 - DEC 21, 2018 VIN Range 1 : Begin : WP0AE2A91JS185065 End : WP0AE2A95JS186171 Vot sequential

Vehicle 10: 2019-2019 Porsche 911 GT3 RS

The information contained in this report was submitted pursuant to 49 CFR §573

19V-875

19V-87 5	Ś
-----------------	---

	Vehicle Type :	LIGHT VEHICLES
	Body Style :	
	Power Train :	GAS
	Descriptive Information :	The recall population was determined based on review of Child Restraint System CRS installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions in the owner's manuals.
	Production Dates :	JUL 05, 2018 - OCT 30, 2019
		Begin : WP0AF2A96KS164064 End : WP0AF2A97KS165952 Vot sequential
	Vehicle 11:	2019-2019 Porsche 911 GT3
	Vehicle Type :	LIGHT VEHICLES
	Body Style :	2-DOOR
	Power Train :	GAS
	Descriptive Information :	The recall population was determined based on review of Child Restraint System CRS installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions in the owner's manuals.
Production Dates : NOV 30, 2018 - APR 29, 2019		NOV 30, 2018 - APR 29, 2019
		2019-2019 Porsche 911 GT2 RS
	• •	LIGHT VEHICLES
	Body Style : Power Train :	
		The recall population was determined based on review of Child Restraint System CRS installation instructions in Owner's Manuals for certain specific high performance versions of 911 vehicles and additionally the Cayman, that are not equipped with the rear designated seating positions present in all other 911 variants. Vehicles outside of the recall population include adequate Restraint System installation instructions in the owner's manuals.
	Production Dates :	DEC 04, 2018 - SEP 25, 2019
	VIN Range 1:	Begin : WP0AE2A98KS155062 End : WP0AE2A94KS155334 📝 Not sequential

The information contained in this report was submitted pursuant to 49 CFR §573

19V-875

Page 5

Description of Noncompliance :

Noncompliance :	The written instruction for CRS installation provided in the Owner's Manual for the subject vehicles may not provide enough specificity to meet the requirements S12(c) of FMVSS No. 225, which requires step-by-step procedure, including diagrams, for properly attaching a child restraint system's tether strap to the tether anchorages.
FMVSS 1 :	225 - Child restraint anchorage systems
FMVSS 2 :	NR
	If the instructions do not provide enough specificity for use of a CRS tether strap, a CRS that utilizes a tether strap may not be installed properly in vehicles with no rear designated seating positions. While Porsche is not aware of any reports of improper CRS installation in the subject vehicles, and has not received any customer complaints on this matter, improper CRS installation could increase the risk of an injury to a child in a CRS in a crash.
Description of the Cause :	Potentially insufficient CRS tether strap installation instructions.
Identification of Any Warning that can Occur :	N/A

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology:

In reviewing Owner's Manual instructions for certain specific high performance versions of 911 vehicles that are not equipped with the rear designated seating positions that are present in all other 911 variants, Porsche began to study whether instructions contained sufficient specificity to meet the requirements of S12(c) of FMVSS No. 225.

While the question of whether current instructions are sufficient is subjective, upon review and out of abundance of caution, Porsche decided to implement Owner's Manual improvements in the affected vehicles, and on December 4, 2019, decided to conduct a recall to provide owners of affected vehicles with a special Owner's Manual supplement.

The information contained in this report was submitted pursuant to 49 CFR §573

Description of Remedy :

Description of Remedy Program :	Porsche will mail all affected vehicle owners an Owner's Manual supplement with enhanced CRS installation instructions.
How Remedy Component Differs from Recalled Component :	
	Vehicles within Porsche's control as well as dealer inventory will be supplied with the supplement until revised manuals are introduced into the vehicle supply chain.

Recall Schedule :

Description of Recall Schedule :	Porsche expects to notify owners within 60 days.
Planned Dealer Notification Date :	FEB 09, 2020 - FEB 09, 2020
Planned Owner Notification Date :	FEB 09, 2020 - FEB 09, 2020

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573