

I-19-05-A

Dear Indian Motorcycle Owner,

Our records indicate that you are the owner of an Indian Motorcycle affected by Safety Recall **I-19-05-A** that was announced on December 12, 2019.

Indian Motorcycle has identified some 2019 Indian (111 c.i.) motorcycles built from 2/12/2019 through 7/31/2019 may have a 10A circuit breaker that does not meet quality standards. Affected circuit breakers do not meet functional specifications and may cause an engine to unexpectedly stop running, increasing the risk of a crash. A letter will arrive at your address by postal mail that provides more information about the update and what you should do next.

Visit our [On-Road Safety Recall](#) page to verify if your Indian Motorcycle is impacted by the recall. Contact your dealer to schedule a service appointment or complete a transfer of ownership if you no longer own the vehicle. Your local Indian Motorcycle dealer can be found on our [Dealer Locator](#) page.

While your dealer is in the best position to answer your questions, you can also call our Indian Motorcycle Customer Connections Department at **1-877-204-3697** to speak with a representative.

Sincerely,

Indian Motorcycle