U.S. Department of Transportation National Highway Traffic Safety Administration

December 18, 2017

Mr. Chris Sandvig Volkswagen Group of America, Inc. 3800 Hamlin Road Auburn Hills, MI 48326

Subject: Fuel Line May Leak Fuel

Dear Mr. Sandvig:

This letter serves to acknowledge Volkswagen Group of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

AUDI/A6/2012-2014 AUDI/A7/2012-2014

Mfr's Report Date: December 6, 2017

NHTSA Campaign Number: 17V-781

Components:

FUEL SYSTEM, GASOLINE: DELIVERY: HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 48,693

Problem Description:

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2012-2014 Audi A6 and A7 vehicles. The fuel line has a compression point that can weaken, potentially resulting in a fuel leak.

Consequence:

A fuel leak in the presence of an ignition source, increases the risk of a fire.

Remedy:

Audi will notify owners, and dealers will replace the fuel line, free of charge. The recall is expected to begin February 5, 2018. Owners may contact Audi customer service at 1-888-237-2834. Volkswagen's number for this recall is 20AR.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150SM 17V-781



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at (202) 366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

