



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

March 26, 2020

Ms. Helen Riehle
Safety Integrity and Recall Manager
BMW of North America, LLC
300 Chestnut Ridge Road
Woodcliff Lake, NJ 07677

NEF-150DM
20E-013

Subject: Brake Fluid Cap Missing Information/FMVSS 122

Dear Ms. Riehle:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/R 1250 GS/2019-2020
BMW/R 1250 GS ADVENTURE/2019-2020
BMW/R 1250 R/2020
BMW/R 1250 RS/2020
BMW/R 1250 RT/2019-2020
BMW/R NINE T/2018-2020
BMW/R NINE T PURE/2019-2020
BMW/R NINE T RACER/2018
BMW/R NINE T SCRAMBLER/2018-2020
BMW/BRAKE FLUID RES. COVER/9999

Mfr's Report Date: March 19, 2020

NHTSA Campaign Number: 20E-013

Components:

SERVICE BRAKES, HYDRAULIC:FLUID

Potential Number of Units Affected: 49

Problem Description:

BMW of North America, LLC (BMW) is recalling certain Motorcycle Accessory Brake Fluid Reservoir Covers, part numbers 8405-752, 8405-753, 8405-754 and 9829547 designed to fit certain 2019-2020 BMW R 1250 motorcycles, and part numbers 8404-098, 8405-100, 8405-102, and 1542056 designed to fit certain 2018-2020 BMW Rnine T motorcycles. The brake fluid reservoir cap may not clearly state the required type of brake fluid and the process for filling the reservoir, possibly leading to an improper maintenance procedure. As such, these caps fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 122, "Motorcycle Brake Systems."

Consequence:

Improper brake system maintenance could affect braking performance and increase the risk of a crash.

Remedy:

BMW will notify owners, and dealers will replace the brake fluid reservoir cap, free of charge. The recall is expected to begin May 11, 2020. Owners may contact BMW customer service at 1-800-525-7417.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- A statement that the defect or noncompliance can cause a vehicle crash without prior warning; or a description of whatever prior warning may occur, and a statement that if this warning is not heeded, a vehicle crash can occur (49 CFR 577.5 (f)(1)).

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be DeMara Magruder who may be reached by phone at (202) 366-8538, or by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement