OMB Control No.: 2127-0004

Recall Quarterly Report

20E-044

Manufacturer Name: Tenneco Automotive NHTSA Recall No. / MFR Recall No.: 20E-044 /

Recall Subject: Rear Suspension Lower Control Rod Failure

Owner Notification Beginning Date: JUL 31, 2020

Owner Notification End Date: JUL 31, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JUL 30, 2021	2021-2	996	70	0	0
3	APR 29, 2021	2021-1	996	70	0	0
2	JAN 22, 2021	2020-4	996	70	0	0
1	OCT 28, 2020	2020-3	996	50	0	0

This Document Last Updated: AUG 02, 2021

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.