

NOTICE OF SAFETY RECALL

Recall No. 20E-087

Dear JDM ASTAR Customer

This notice is sent to you in accordance with the requirement of the National Traffic and Motor Vehicle Safety Act. JDM ASTAR LLC has decided that T1 headlamp fail to conform to Federal Motor Vehicle Safety Standard No. 108, Lamps, reflective devices and associated equipment. Accordingly, we are initiating this safety recall. Please review this letter carefully

Item Covered Under Recall

The T1 Headlamp Bulb sizes H11, 9005, 9006, H4, 9007, H13, and 9012 was marketed as a replaceable headlight bulb on vehicles. The recall covers only bulbs sold in the United States.

Noncompliance of Recalled Item

The T1 replaceable light source's maximum luminous flux was above the maximum limit during about the first ten minutes, then falls within legal limits; there are dimensional requirements that were not met in that there are no resistive filaments; and that it does not conform with marking requirements.

Safety Risk

The maximum luminous flux was above the maximum limit and may cause excessive brightness, to oncoming drivers increasing the risk of a crash.

What to do Next.

If you own the JDM ASTAR T1 headlamp bulb, please return the bulbs with your name, address, order number, phone number, email and date of purchase, to JDM ASTAR LLC obtain a full refund.

The return address is JDM ASTAR LLC
 15306 Valley Blvd
 City of Industry CA 91746

If you have questions, please email us recall@jdmastar.com or call us at 626-330-0711.

We appreciate your cooperation and prompt attention to this important matter and apologize for any inconvenience.

Sincerely
JDM ASTAR LLC