



Triumph Motorcycles America Ltd.
100 Hartsfield Centre Parkway
Suite 200
Atlanta, Georgia 30354

24th February 2020

! IMPORTANT SAFETY RECALL !

REPLACEMENT SIDE STAND SPRING TO PREVENT ENGINE STALL

Safety Recall: SRAN570
NHTSA Recall: 20V015

This notice applies to your motorcycle:

Model: 2016 to 2020 - Thruxton, Thruxton R, and Thruxton TFC
VIN: SMTXX

Dear [NAME F&L]:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Triumph Motorcycles Ltd. has decided that a defect which relates to motor vehicle safety exists in your motorcycle, with the VIN shown above. Accordingly, Triumph Motorcycles America Ltd. is conducting a safety recall to address the condition.

The reason for this recall notice: The side stand spring may fracture whilst the motorcycle is being ridden resulting in an engine stall. An engine stall without warning may increase the risk of a crash.

What Triumph & your dealer will do: Triumph Motorcycles America Ltd. has authorized your dealer to replace the side stand spring, free of charge to you (parts and labour). This repair should take less than 10 minutes. However, depending upon the dealer's work schedule, it may be necessary to make your motorcycle available for a longer period of time.

What you must do to ensure your safety: Please make an appointment with your authorized Triumph motorcycles dealer to have this important remedy performed on your motorcycle as soon as possible.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you need help: Please contact your authorized Triumph dealer should you have any questions or encounter any difficulty regarding this recall. In the event your dealer is unable to remedy your motorcycle, please contact Triumph Motorcycles America at 1-678-854-2010.

If an authorized Triumph dealer or Triumph Motorcycle America Ltd fails or is unable to perform this remedy without charge within a reasonable amount of time, you may contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C., 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own the motorcycle listed above, please contact Triumph at 1-678-854-2010 and provide any information you can furnish that will assist us in locating the new owner.

We apologise for any inconvenience this may cause you. However, we have taken this action in the best interest of your safety and your continued satisfaction with your Triumph motorcycle. We appreciate your attention and cooperation in this important matter.

Sincerely

Triumph Motorcycles America Ltd.