

Service Bulletin

20-008

January 22, 2020 Version 1

Safety Recall: Driver's Frontal Airbag Inflator

Year	Model	Trim	VIN Range
1998-2000	Accord	ALL	Check the iN VIN status for eligibility.
1996-2000	Civic	ALL	Check the iN VIN status for eligibility.
1997-2001	CR-V	ALL	Check the iN VIN status for eligibility.
1997-98	EV Plus	ALL	Check the iN VIN status for eligibility.
1998-2001	Odyssey	ALL	Check the iN VIN status for eligibility.

When this temporary placeholder bulletin appears during an iN VIN Status Inquiry, this vehicle is subject to a Safety Recall related to the driver's frontal airbag inflator. Parts are not available, however, vehicles may be serviced with a customer acknowledgement. Include the suggested verbiage below on the RO:

The vehicle is subject to a safety recall affecting the driver's frontal airbag inflator. Redesigned airbag inflators are not available for installation at this time. Once redesigned parts are available, the registered owner of the vehicle will receive notice to bring the vehicle in for an inspection and, as necessary, replacement of the component.

Refrain from calling Tech Line for updates. This placeholder will be updated as information becomes available along with an updated iN message.

For any questions or concerns that customers may have, you may direct them to contact American Honda's Customer Support & Campaign Center at **888-234-2138**.

END

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.