

# Recall Quarterly Report

## 20V-099

**Manufacturer Name :** Ford Motor Company  
**NHTSA Recall No. / MFR Recall No. :** 20V-099 / 20S09  
**Recall Subject :** Driveshaft May Separate From Rear Axle  
**Owner Notification Beginning Date :** MAR 19, 2020  
**Owner Notification End Date:** MAR 19, 2020



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2        | JUL 29, 2020    | 2020-2         | 319               | 265            | 7                 | 0             |
| 1        | APR 22, 2020    | 2020-1         | 319               | 86             | 56                | 0             |

This Document Last Updated : JUL 30, 2020

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.