

March 12, 2020

Mr. Garett Carolus Keystone RV Company P.O. Box 2000 Goshen, IN 46527

Subject: Missing Egress Window

Dear Mr. Carolus:

This letter serves to acknowledge Keystone RV Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: KEYSTONE/BULLET/2020

Mfr's Report Date: February 27, 2020

NHTSA Campaign Number: 20V-118

Components: STRUCTURE:BODY:DOOR/WINDOW:EMERGENCY EXIT

Potential Number of Units Affected: 27

Problem Description:

Keystone RV Company (Keystone) is recalling certain 2020 Bullet 34RI trailers equipped with overhead cabinets across the rear wall. The trailers may be missing an egress window in the main living area, preventing passenger exit in the event of an emergency.

Consequence:

In the event of an emergency, the missing egress window can lengthen the time that passengers need to exit the vehicle, increasing the risk of injury.

Remedy:

Keystone will notify owners, and dealers will replace the existing crank open vent window with an egress window, free of charge. The recall is expected to begin April 21, 2020. Owners may contact Keystone customer service at 1-866-425-4369.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150KL 20V-118

We have received Keystone's proposed owner notification letter and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kristin Lepper who may be reached by phone at 202-366-5227, or by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

