



*Manufacturier de semi-remorques citernes
Manufacturer of tank trailers*

IMPORTANT SAFETY RECALL 20V-159

This notice applies to your vehicle(s)

Tremcar reference Unit number	VIN
19667	1T9AA98

March 30th, 2020

Dear owner/dealer/reseller,

This notice is sent to you in accordance with the requirements of the National Highway Traffic and Motor Vehicle Safety Act.

TSE Brakes (a Hendrickson's subcontractor) has decided that a limited number of brake actuators manufactured between 7/24/2018 and 8/10/2018 have a Safety Defect involving the flat mounting washer used to fasten the brake actuator to the mounting bracket on the vehicle. The washers used for mounting the actuators may fracture, allowing the actuators to loosen, potentially reducing the braking ability.

Your brake actuator mounting hardware is being recalled. A reduction in the braking performance can lengthen the distance needed to stop the vehicle, increasing the risk of a crash.

You should contact TSE Brakes immediately to order replacement mounting hardware. The replacement brake actuator mounting washers and nuts, will be installed free of charge. The estimated time for inspection and repair is 0.25 hours.

For further information and to schedule the replacement please contact Tyler McGuire at 256-735-2284 or tyler.mcguire@tsebrakes.com (and general e-mail customer.service@tsebrakes.com) to arrange for the shipment of new mounting hardware and for labor reimbursement.

If after having attempted to take advantage of this recall you believe you have not been able to have your trailer remedied without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

TREMCAR apologize for any inconvenience this safety recall may cause, but your safety is our first concern.



Corey Kirk
Warranty Manager

Enclosure : Notifications of Hendrickson and TSE Brakes