

Recall Quarterly Report

20V-171

Manufacturer Name : Newmar Corporation
NHTSA Recall No. / MFR Recall No. : 20V-171 / #20V-127
Recall Subject : Insufficiently Tightened Brake Caliper Bolts
Owner Notification Beginning Date : MAY 06, 2020
Owner Notification End Date: MAY 08, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	OCT 29, 2020	2020-3	129	101	0	0
1	JUL 31, 2020	2020-2	129	85	0	0

This Document Last Updated : NOV 10, 2020

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.