

U.S. Department of Transportation

National Highway Traffic Safety Administration

March 30, 2020

Mr. Greg Gunther Department Manager VCA Mercedes-Benz USA, LLC. 13470 International Parkway Jacksonville, FL 32218

Subject: Engine Oil Plugs May Leak

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150JK

20V-173

Makes/Models/Model Years:

MERCEDES BENZ/S560/2018-2019 MERCEDES-MAYBACH/S560/2018-2019

Mfr's Report Date: March 20, 2020

NHTSA Campaign Number: 20V-173

Components:

ENGINE

Potential Number of Units Affected: 9,791

Problem Description:

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2018-2019 S560 and Maybach S560 vehicles equipped with 4.0L 8-cylinder gasoline-engines. Two engine oil plugs may not withstand high engine loads while driving, possibly resulting in an engine oil leak.

Consequence:

An engine oil leak can spill on to the road and cause slippery road conditions. Additionally, if the engine runs out of oil it can cause an engine stall while driving. Either of these scenarios can increase the risk of a crash.

Remedy:

MBUSA will notify owners, and dealers will replace the engine oil plugs, free of charge. The recall is expected to begin May 19, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received MBUSA's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff

Chief, Recall Management Division Office of Defects Investigations

Enforcement

